Attachment B-4

Photographic Documentation of Site Reconnaissance (27-31 July 1998)




Photo A1 [7/27/98-14:00]

Site 150(7) Former Motor Pool Area 1000 and parking area [CERFA Parcel Map:17,39] photo faces toward the south. The photo depicts an area covered by paved roads, parking lots, buildings, and maintained grass areas. There are stands of deciduous tress surrounding the area. The area behind the building appears to be parcel 13(7). Site 139(7) is covered by the parking lot.



Photo B1 [7/28/98-15:07]
Photo depicts a dirt road near Cave Creek Seep (APEC MP5); seep emerging from hill.



Photo B2 [7/28/98-15:07]
Photo at the same locaton as photo B1 (off of Bane's Gap Road); example of longleaf pine and deciduous forest.



Photo B3 [7/28/98-15:17]
Photo is taken pointing to the southeast at a 5-way intersection of a dirt road northeast of the Stump Dump. Photo depicts a small open field surrounded by long-leaf pine.